




<p>x 50</p> <p>(a)</p>	<p>x 6</p> <p>(b)</p>	<p>x 6</p> <p>(c)</p>	<p>x 8</p> <p>(d)</p>	
<p>x 10</p> <p>(h)</p>	<p>x 23 (3,5x30)</p> <p>(i)</p>	<p>x 68 (3,5x16)</p> <p>(j)</p>	<p>x 125</p> <p>(k)</p>	<p>x 1</p> <p>(l)</p>
<p>x 5 kpl.(400 mm)</p> <p>(e)</p>	<p>x 4</p> <p>(f)</p>	<p>x 1 (570 mm)</p> <p>(g)</p>		



① - FAZY MONTAŻU

Ⓐ - OZNACZENIE ELEMENTÓW

Ⓐ - OZNACZENIE AKCESORIÓW

