


	QTY	mm
1	1	1110x90x40
2	1	1110x90x40
3	1	430x90x20
4	1	430x90x20
5	1	620x90x20
6	1	620x90x20
7	1	290x90x20
8	1	290x90x20
9	3	570x90x20
10	2	570x90x20
11	1	192x90x20
12	1	192x90x20
13	1	650x90x20
14	1	650x90x20
15	1	590x90x20
16	1	590x90x20
17	2	1150x43x25
18	1	700x68x20
19	1	700x90x20
20	1	1670x695x17


Tools needed (not supplied)





A		8x40	x46
B		8x30	x6
C		7x60	x8
D		7x50	x2
E		D35	x8
F		7x34	x2
G		15x12	x2
H		3,5x40	x6


J		5x38	x4
K		6,3x50	x12
L		D15x18	x12
M		D18	x2
N		D4x13	x2
P		D35	x2
Q		D15x3	x6
R		4mm	x1


①






A		8x40	x46
B		8x30	x6

②





C		7x60	x8
---	---	------	----

3






E		D35	x4
---	--	-----	----

4




J		5x38	x4
---	--	------	----

5




F		7x34	x2
---	---	------	----



6





1.






2.





G		15x12	x2
M		D18	x2

7



E		D35	x4
P		D35	x2


8





N		D4x13	x2
L		D15x18	x2


K		6,3x50	x2
D		7x50	x2



9





K		6,3x50	x6
L		D15x18	x6

10




K		6,3x50	x4
L		D15x18	x4

11



H		3,5x40	x6
---	---	--------	----

12



Q		D15x3	x6
---	---	-------	----