



PORTO

→ 135 ↑ 190 ↘ 31



x 30 a	x 16 b	x 9 c	x 9 d	x 6 e	x 6 f
x 4 (M4-12) i	x 4 j	x 1 kpl. k	x 2 l	x 1 m	x 5 n
x 2 r	x 2 s	x 8 (6,2x16) t	x 8 (3,5x30) u	x 38 (3,5x16) w	x 100 y
x 9 g	x 4 (182 mm) h	x 1 (250 mm) o	x 1 kpl. p	 w	 60 min

1 - FAZY MONTAŻU

A - OZNACZENIE ELEMENTÓW

a - OZNACZENIE AKCESORIÓW



